



ASSET INSPECTION PROJECT

2013— TRANSMISSION LINE— ABOVE GROUND INSPECTION SERVICES

*THROUGHOUT CMP SERVICE TERRITORY
STATE OF MAINE*

DESCRIPTION:

Complete inspection and field data recording of transmission line structure condition with exception of the pole ground line inspection and treatment.

PROJECT TASKS:

Project specific crew training covering data recording requirements and project execution procedures. Approximately (5,000) poles were assessed for pole stability and climbed to inspect for pole and crossarm integrity, and brace decay. Inspection of hardware for tightness and integrity. During the inspection process, hardware identified as loose was tightened as per detail specifications. Installation of pole and aerial tags. All work performed by qualified line workers under energized work conditions using 100% fall protection.

5,124—Safely Worked Hours—Incident Free

OWNER:

Central Maine Power/Iberdrola-USA

CLIENT REFERENCE:


Central Maine Power
83 Edison Drive
Augusta, Maine 04330

Art Brown, Transmission Maintenance
Coordinator

Tel: 207-626-9562



Real Time Data Transfer



***Electrical Line Construction & Maintenance
Since 1963***